

Aircraft Make	Aircraft Model	Heater Part Number
Piper Cheyenne	I & II	FR10E21-4(IS)
Cessna	414	FR13E55-1(IS)
Cessna	421	FR13E55-1(IS)
Cessna	340A	FR13E55-2(IS)
Piper Twin Comanche	PA-30, PA-39	FR20D35-1(IS)
Piper Aztec	PA-23 (12v)	FR37D77-1(IS)
Piper Chieftain / T-1020	PA-31-350	FR65D79-3(IS)
Beech Baron	B55 s/n TC-1658 on	FR81D94-3(IS)
Beech Baron	E55 s/n TE-959, TE968 on	FR81D94-3(IS)
Beech Baron	58 Series s/n TJ-437 on	FR81D94-3(IS)
Piper Seneca I-III	PA-34 (12v)	FR90D38-1(IS)
Piper Seminole	PA-44 (12v)	FR90D38-2(IS)
Piper Seneca III-V	PA-34 (24v)	FR91E88-1(IS)
Cessna	310I-Q	FR96C62-1(IS)
Cessna	T310P-Q	FR96C62-1(IS)
Cessna	320C-F	FR96C62-1(IS)
Piper Navajo	PA-31-350	FRD39D59(IS)

Replaces Aircraft Heater Part Number	2016 List Price	Core Charge
755 244, 755 261, 755 283, 755 286, 755 307, 755 334	\$4,850.00	\$500.00
9910004-11, 9910305-1, -7	\$4,899.00	\$500.00
9910004-11, 9910305-1, -7	\$4,899.00	\$500.00
9910305-8	\$4,899.00	\$500.00
464 346, 751 959	\$4,299.00	\$500.00
751 978, 755 256	\$4,250.00	\$500.00
755 234, 755 248, 755 263, 755 311	\$4,650.00	\$500.00
58-380057-3, -7, -9	\$4,225.00	\$500.00
58-380057-3, -7, -9	\$4,225.00	\$500.00
58-380057-3, -7, -9	\$4,225.00	\$500.00
78355-05, 464 401	\$4,225.00	\$500.00
464 427	\$4,225.00	\$500.00
689 940	\$4,225.00	\$500.00
0813841-1, -9	\$4,225.00	\$500.00
0813841-1	\$4,225.00	\$500.00
0813841-1, -9	\$4,225.00	\$500.00
755 234, 755 273, 755 312	\$4,299.00	\$500.00