

#### Hartzell Engine Technologies LLC 2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# AIRCRAFT STARTER & PARTS PRICE LIST

**RELEASE DATE** » January 2, 2013 **AUTHOR** » HET Sales Department **REV** » Original: Formatted to HET Design Standards

Hartzell Engine Technologies (HET) is the leading OEM supplier of aircraft cabin heating solutions and engine accessories, including turbocharging systems, alternators, starters, and fuel pumps.

NOTE The following statements are excerpts from the FAA Advisory Circular 20-62C entitled "ELIGIBILITY, QUALITY, AND IDENTIFICATION OF APPROVED REPLACEMENT PARTS" All HET products offered herein meet the requirement of FAA Advisory Circular 20-62C.

## **FAA Advisory Notice » Background**

An increasing amount of replacement parts (including standard parts), materials, appliances and instruments are offered forsales as being of aircraft quality and origin of these units are unknown. Users of such units are usually not aware of the potential hazards involved with replacement parts that are not eligible for use on certified aircraft. Frequently such units are deceptively advertised and presented as "unused," "like new," or "remanufactured." This implies that the quality of such units is equal to an original or appropriately repaired or overhauled.

The performance rules for replacement of parts and materials used in the maintenance and alteration of U.S. certificated aircraft are specified in Federal Aviation Regulations (FAR) 43.13 and FAR 145.57. The responsibility for the continued airworthiness of the aircraft, which includes the replacement of parts, is the responsibility of the owner/operator as outlined in FAR 91.163, FAR 121.363, FAR 123.45, FAR 127.131 and FAR 135.143 (a).

### **Identification of the Approved Parts**

Approved serviceable replacement parts are identified as follows:

- By an FAA Form 8130-3 (Formerly FAA Form 186), Airworthiness Approval Tag. An Airworthiness Approval Tag identifies a part or group of parts that have been approved by an authorized FAA representative.
- By an FAA Technical Standard Order (TSO) number and identification mark that indicates the part or appliance has been manufactured under the requirements of FAR 37.
- By an FAA/PMA symbol, together with the manufacturer's name, trademark or symbol, part number, and the make and model of the type certificated product on which the part is eligible for installation, stamped on the part. An FAA Parts Manufacturer Approval (FAA/PMA) is issued under FAR 21.305. The make and model information may be on a tag attached to the part.
- By shipping ticket, invoice, or other document which provides evidence that the part was produced by a manufacturer holding an FAA Approved Production Inspection System issued under FAR 21, Subpart F, or by a manufacturer holding an FAA Production Certificate issued under FAR 21, Subpart G.



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

 By a certificate of airworthiness for export issued by a foreign government under the provisions of FAR 21, Subpart N.

# **Know Your Supplier**

It has come to our attention that many reproduced parts and components, particularly instruments which have been manufactured by persons other than the original manufacturer, are available for purchase and installation on U.S. certificated aircraft. Often, an original part is used as a sample to produce duplicates. The reproduced parts appear to be as good as the original part; however, there are many unknown factors to be considered that may not be readily apparent to the purchaser, i.e. heat treating, plating, inspections, tests, and calibrations. All too often the faulty part is not discovered until a malfunction or an accident occurs.

### **Summary**

In accordance with FAR's, certification of materials, parts, and appliances for return to service, for use on aircraft, is the responsibility of the person or agency who signs the approval. The owner/operator, as denoted in paragraph 3 of this advisory circular, is responsible for the continued airworthiness of the aircraft. To assure continued safety in aircraft operation, it is essential that great care be used when inspecting, testing and determining the acceptability of all parts and materials. Particular caution should be exercised when the identity of materials, parts, and appliances cannot be established or when their origin is in doubt.

### **General Terms & Conditions**

- All prices are subject to change without notice. Invoice prices will be seller's price in effect at time of shipment.
- All prices are F.O.B. Hartzell Engine Technologies plant point of shipment.
- All prices in this catalog are less sales and excise taxes. All quotations and/or contracts shall be subject to increase without notice by the amount of any sales, use or excise taxes levied against such transactions by any Federal, State, Municipal or other domestic or foreign government agency unless tax exemption certificate can be furnished which will meet the approval of such agency.
- All orders are payable in U.S. funds.
- Hartzell Engine Technologies is not responsible for any part left on the unit which is not part of the normal overhaul.
- HET reserves the right to return any unit that cannot be overhauled disassembled.



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **TABLE OF CONTENTS**

| SECTION »  | PAGE # |
|--|--------|
| FAA Advisory Notice  | 01     |
| Know Your Supplier   | 02     |
| Summary  | 02     |
| General Terms and Conditions   | 02     |
| Table of Contents  | 03     |
| Factory New Aircraft Starters  |        |
| Aircraft Starters for Lycoming Engines   | 04     |
| Continental Motors (CM) Engine Starters from HET   | 06     |
| Overhaul / Exchange Aircraft Starters  |        |
| Lycoming Engine Starter Overhaul / Exchange  |        |
| <ol> <li>Continental Motors (CM) Engine Starters Overhaul / Exchange</li> <li>Starter Overhaul Kits</li> </ol> |        |
| Parts Section  |        |
| 6. Aircraft Starter Replacement Parts  | 12     |
| <b>General Warranty Policy</b>   |        |
| 7. Limited Warranty Policy   | 19     |
| 8. Limitations and Exclusions  | 20     |
| 9. Warranty Registration   |        |
| 10. Specific Terms11. General  |        |
| 11. General  | 21     |
| Core Return & Return Goods Policy  |        |
| 12. Core Chargeback Policy   |        |
| 13. Return Goods Policy  | 23     |

#### Aircraft Starter & Parts Price List Rev. Original



Rev. Original January 2, 2013

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **FACTORY NEW AIRCRAFT STARTERS**

Two (2) Years\* Unlimited Hours Warranty on New E-Drive, X-Drive, and M-Drive Aircraft Starters: Read full policy on pg 19. For more info: www.hartzellenginetech.com/aircraft-parts/aircraft-starter.html

| 1. Aircraft Starters for Lycoming Engines » Factory New |  |            |             |
|---|--|------------|-------------|
| Part Number   | Description  | List Price | Core Charge |
| ELB-8011  | E-Drive Reverse Direction Aircraft Starter 24V, 12/14 Pitch,149 Tooth » Replaces Sky-Tec 149-NLR/ec, Lycoming 31B26900 | \$750.00   |             |
| ELZ-8021  | E-Drive Reverse Direction Aircraft Starter 12V, 12/14 Pitch,149 Tooth » Replaces Sky-Tec 149-NLR Lycoming 31A26901     | \$704.00   |             |
| ERB-8011  | E-Drive Starter 24V, 12/14 Pitch, 149 Tooth » Replaces Sky-Tec 149-NL, 149-NL/ec, Lycoming 31B26040                    | \$736.00   |             |
| ERB-8012  | E-Drive Starter 24V, 10/12 Pitch,122 Tooth » Replaces Sky-Tec 122-NL, 122-NL/ec, Lycoming 31B26042                     | \$736.00   |             |
| ERZ-8011  | E-Drive Aircraft Starter 12V, 12/14 Pitch, 149 Tooth » Replaces Sky-Tec 149-NL, Lycoming 31A26041                      | \$680.00   |             |
| ERZ-8012  | E-Drive Aircraft Starter 12V, 10/12 Pitch, 122 Tooth » Replaces Sky-Tec 122-NL, Lycoming 31A26043                      | \$680.00   |             |
| SRB-9021  | X-Drive Aircraft Starter LH Solenoid 24V, 12/14 Pitch, 9 Tooth » Replaces Sky-Tec 149-24HT, 149-24LS                   | \$672.00   |             |
| SRB-9022  | X-Drive Aircraft Starter LH Solenoid 24V, 10/12 Pitch, 9 Tooth » Replaces Sky-Tec 122-24PM                             | \$672.00   |             |
| SRB-9031  | X-Drive Aircraft Starter RH Solenoid 24V, 12/14 Pitch, 9 Tooth » Replaces Sky-Tec 149-24PM                             | \$672.00   |             |
| SRB-9032  | X-Drive Aircraft Starter RH Solenoid 24V, 10/12 Pitch, 9 Tooth » Replaces Sky-Tec 122-24PM                             | \$672.00   |             |
| SRZ-9021  | X-Drive Aircraft Starter LH Solenoid 12V, 12/14 Pitch, 9 Tooth » Replaces Sky-Tec 149-12LS                             | \$608.00   |             |
| SRZ-9022  | X-Drive Aircraft Starter LH Solenoid 14V, 10/12 Pitch, 9 Tooth » Replaces Sky-Tec 122-12LS                             | \$608.00   |             |
| SRZ-9031  | X-Drive Aircraft Starter RH Solenoid 12V, 12/14 Pitch, 9 Tooth » Replaces Sky-Tec 149-12PM                             | \$608.00   |             |
| SRZ-9032  | X-Drive Aircraft Starter RH Solenoid 14V, 10/12 Pitch, 9 Tooth » Replaces Sky-Tec 122-12PM                             | \$608.00   |             |



Rev. Original January 2, 2013

| 1. Aircraft Sta | arters for Lycoming Engines » Factory New       |            |             |
|-----------------|---|------------|-------------|
| Part Number     | Description                                     | List Price | Core Charge |
| MHB-4001        | Replaced by MHB-4016                            |            |             |
| MHB-4001R       | Replaced by MHB-4016                            |            |             |
| MHB-4003        | Replaced by MHB-4020                            |            |             |
| MHB-4003R       | Replaced by MHB-4020                            |            |             |
| MHB-4007        | Replaced by MHB-4018                            |            |             |
| MHB-4007R       | Replaced by MHB-4018                            |            |             |
| MHB-4009        | Replaced by MHB-4014                            |            |             |
| MHB-4009R       | Replaced by MHB-4014                            |            |             |
| MHB-4010        | Replaced by MHB-4016                            |            |             |
| MHB-4010R       | Replaced by MHB-4016                            |            |             |
| MHB-4012        | Replaced by MHB-4020                            |            |             |
| MHB-4012R       | Replaced by MHB-4020                            |            |             |
| MHB-4013        | Replaced by MHB-4018                            |            |             |
| MHB-4013R       | Replaced by MHB-4018                            |            |             |
| MHB-4014        | 24V Aircraft Starter, Gear Reduction ***LW14214 | \$1,204.00 | \$200.00    |
| MHB-4015        | Replaced by MMU-4001                            |            |             |
| MHB-4015R       | Replaced by MMU-4001                            |            |             |
| MHB-4016        | 24V Aircraft Starter, Gear Reduction            | \$1,424.00 |             |
| MHB-4018        | Replaced by ERB-8011                            |            |             |
| MHB-4019        | Replaced by MHB-4020                            |            |             |
| MHB-4019A       | Replaced by MHB-4020                            |            |             |
| MHB-4019R       | Replaced by MHB-4020                            |            |             |
| MHB-4020        | Replaced by ERB-8011                            |            |             |
| MHB-6014        | 24V Aircraft Starter, 12/14 Pitch, 149 Tooth    | \$930.00   |             |
| MHJ-4002        | Replaced by MHJ-4003S                           |            |             |
| MHJ-4003S       | 24V Aircraft Starter, Direct Drive              | \$1,382.00 |             |
| MMU-4001        | Replaced by ERB-8012                            |            |             |
| MZ-4205         | Replaced by MZ-4226                             |            |             |
| MZ-4205R        | Replaced by MZ-4226                             |            |             |



Rev. Original January 2, 2013

| 1. Aircrafts | Starter for Lycoming Engines » Factory New                   |            |             |
|--------------|--|------------|-------------|
| Part Number  | Description  | List Price | Core Charge |
| MZ-4206      | Replaced by MZ-4222  |            |             |
| MZ-4206R     | Replaced by MZ-4222  |            |             |
| MZ-4216      | Replaced by MZ-4220  |            |             |
| MZ-4216R     | Replaced by MZ-4220  |            |             |
| MZ-4217      | Replaced by MZ-4226  |            |             |
| MZ-4217R     | Replaced by MZ-4226  |            |             |
| MZ-4218      | Replaced by MZ-4222  |            |             |
| MZ-4218R     | Replaced by MZ-4222  |            |             |
| MZ-4220      | Replaced by MZ-6220  |            |             |
| MZ-4221      | Replaced by MZ-4226  |            |             |
| MZ-4221R     | Replaced by MZ-4226  |            |             |
| MZ-4222      | 12V Aircraft Starter, Gear Reduction                         | \$1,382.00 |             |
| MZ-4226      | Replaced by ERZ-8011   |            |             |
| MZ-6220      | 12V Aircraft Starter, 12/14 Pitch, 149 Tooth                 | \$784.00   |             |
| PM1201       | 12V Aircraft Starter, 12/14 Pitch, 149 Tooth                 | \$714.00   |             |
| PM1203       | 12V Aircraft Starter, 10/12 Pitch, 122 Tooth                 | \$778.00   |             |
| PM1204       | 12V Aircraft Starter, Counter-rotating                       | \$778.00   |             |
| PM2401       | 24V Aircraft Starter, 12/14 Pitch, 149 Tooth                 | \$742.00   |             |
| PM2403       | 24V Aircraft Starter, 10/12 Pitch, 122 Tooth                 | \$742.00   |             |
| PM2404       | 24V Aircraft Starter, Counter-rotating                       | \$742.00   |             |
| 2. Continent | tal Motors Aircraft Starter » Factory New                    |            |             |
| Part Number  | Description  | List Price | Core Charge |
| MRB-7000     | M-Drive Aircraft Starter - Factory New, 24V                  | \$904.00   |             |
| MRZ-7000     | M-Drive Aircraft Starter - Factory New, 12V                  | \$904.00   |             |
| ES646238-2   | Starter (TCM Energizer Replacement) - 12V, Direct Drive      | \$778.00   |             |
| ES646238-3   | Starter (TCM Energizer Replacement) - 12V, Direct w/Solenoid | \$778.00   |             |
| ES646275-1   | Starter (TCM Energizer Replacement) - 24V, Direct Drive      | \$840.00   |             |
| PM1207       | 12V Aircraft Starter   | \$788.00   |             |
| PM1207       | 24V Aircraft Starter   | \$788.00   |             |





Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **OVERHAUL / EXCHANGE AIRCRAFT STARTERS**

**Limited Six (6) Months\* Warranty on Overhauled Components:** Read full policy on page 19. For more info please visit: www.hartzellenginetech.com/aircraft-parts/aircraft-starter.html

| 3. Lycoming | Engine Starters » Overhaul / Exchange |            |             |
|-------------|---------------------------------------|------------|-------------|
| Part Number | Description                           | List Price | Core Charge |
| MCL-6501R   | 12V Aircraft Starter                  | \$498.00   | \$150.00    |
| MHB-4001    | Replaced by MHB-4016R                 |            |             |
| MHB-4001R   | Replaced by MHB-4016R                 |            |             |
| MHB-4002    | Replaced by MHB-4017R                 |            |             |
| MHB-4002R   | Replaced by MHB-4017R                 |            |             |
| MHB-4003    | Replaced by MHB-4020R                 |            |             |
| MHB-4003R   | Replaced by MHB-4020R                 |            |             |
| MHB-4004R   | 24V Aircraft Starter                  | \$1,212.00 | \$175.00    |
| MHB-4005R   | 24V Aircraft Starter                  | \$1,212.00 | \$235.00    |
| MHB-4007    | Replaced by MHB-4018R                 |            |             |
| MHB-4007R   | Replaced by MHB-4018R                 |            |             |
| MHB-4008    | Replaced by MHB-4008R                 |            |             |
| MHB-4008R   | 24V Aircraft Starter                  | \$692.00   | \$134.00    |
| MHB-4009    | Replaced by MHB-4014R                 |            |             |
| MHB-4009R   | Replaced by MHB-4014R                 |            |             |
| MHB-4010    | Replaced by MHB-4016R                 |            |             |
| MHB-4010R   | Replaced by MHB-4016R                 |            |             |
| MHB-4011    | Replaced by MHB-4017R                 |            |             |
| MHB-4011R   | Replaced by MHB-4017R                 |            |             |
| MHB-4012    | Replaced by MHB-4020R                 |            |             |
| MHB-4012R   | Replaced by MHB-4020R                 |            |             |
| MHB-4013    | Replaced by MHB-4018R                 |            |             |
| MHB-4013R   | Replaced by MHB-4018R                 |            |             |
| MHB-4014    | Replaced by MHB-4014R                 |            |             |



Rev. Original January 2, 2013

| 3. Lycoming | Engine Starters » Overhaul / Exchange |            |             |
|-------------|---------------------------------------|------------|-------------|
| Part Number | Description                           | List Price | Core Charge |
| MHB-4014R   | 24V Aircraft Starter                  | \$820.00   | \$200.00    |
| MHB-4015    | Replaced by MMU-4001R                 |            |             |
| MHB-4015R   | Replaced by MMU-4001R                 |            |             |
| MHB-4016    | Replaced by MHB-4016R                 |            |             |
| MHB-4016R   | 24V Aircraft Starter                  | \$820.00   | \$200.00    |
| MHB-4017    | Replaced by MHB-4017R                 |            |             |
| MHB-4017R   | 24V Aircraft Starter                  | \$714.00   | \$200.00    |
| MHB-4018    | Replaced by MHB-4018R                 |            |             |
| MHB-4018R   | 24V Aircraft Starter                  | \$820.00   | \$200.00    |
| MHB-4019    | Replaced by MHB-4020R                 |            |             |
| MHB-4019A   | Replaced by MHB-4020R                 |            |             |
| MHB-4019R   | Replaced by MHB-4020R                 |            |             |
| MHB-4020    | Replaced by MHB-4020R                 |            |             |
| MHB-4020R   | 24V Aircraft Starter                  | \$714.00   | \$200.00    |
| MHJ-4002    | Replaced by MHJ-4003SR                |            |             |
| MHJ-4003    | Replaced by MHJ-4003SR                |            |             |
| MHJ-4003SR  | 24V Aircraft Starter                  | \$546.00   | \$190.00    |
| MHJ-4004    | Replaced by MHJ-4004R                 |            |             |
| MHJ-4004R   | 24V Aircraft Starter                  | \$1,336.00 | \$300.00    |
| MHJ-4005    | Replaced by MHJ-4005R                 |            |             |
| MHJ-4005R   | 24V Aircraft Starter                  |            |             |
| MHJ-4101S   | Replaced by MHJ-4003SR                |            |             |
| MHP-4101    | Replaced by MHJ-4003SR                |            |             |
| MMU-4001    | Replaced by MMU-4001R                 |            |             |
| MMU-4001R   | 24V Aircraft Starter                  | \$778.00   | \$200.00    |
| MZ-4204     | Replaced by MZ-4204R                  |            |             |
| MZ-4204R    | 12V Aircraft Starter                  | \$682.00   | \$165.00    |
| MZ-4205     | Replaced by MZ-4217R                  |            |             |
| MZ-4205R    | Replaced by MZ-4217R                  |            |             |
| MZ-4206     | Replaced by MZ-4222R                  |            |             |
| page 8      |                                       |            |             |



Rev. Original January 2, 2013

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

| 3. Lycoming | Engine Starters » Overhaul / Excha | nge        |             |
|-------------|------------------------------------|------------|-------------|
| Part Number | Description                        | List Price | Core Charge |
| MZ-4206R    | Replaced by MZ-4222R               |            |             |
| MZ-4207     | Replaced by MZ-4219R               |            |             |
| MZ-4207R    | Replaced by MZ-4219R               |            |             |
| MZ-4208     | Replaced by MZ-4208R               |            |             |
| MZ-4208R    | 12V Aircraft Starter               | \$596.00   | \$124.00    |
| MZ-4214R    | 12V Aircraft Starter               | \$904.00   | \$100.00    |
| MZ-4216     | Replaced by MZ-4220R               |            |             |
| MZ-4216R    | Replaced by MZ-4220R               |            |             |
| MZ-4217     | Replaced by MZ-4217R               |            |             |
| MZ-4217R    | 12V Aircraft Starter               | \$714.00   |             |
| MZ-4218     | Replaced by MZ-4222R               |            |             |
| MZ-4218R    | Replaced by MZ-4222R               |            |             |
| MZ-4219     | Replaced by MZ-4219R               |            |             |
| MZ-4219R    | 12V Aircraft Starter               |            |             |
| MZ-4220     | Replaced by MZ-4220R               |            |             |
| MZ-4220R    | 12V Aircraft Starter               | \$714.00   | \$200.00    |
| MZ-4221     | Replaced by MZ-4217R               |            |             |
| MZ-4221R    | Replaced by MZ-4217R               |            |             |
| MZ-4222     | Replaced by MZ-4222R               |            |             |
| MZ-4222R    | 12V Aircraft Starter               | \$714.00   | \$200.00    |
| MZ-4223     | Replaced by MZ-4219R               |            |             |
| MZ-4223R    | Replaced by MZ-4219R               |            |             |
| MZ-4224     | Replaced by MZ-4224R               |            |             |
| MZ-4224R    |                                    | \$714.00   | \$200.00    |
| MZ-4225     | Replaced by MZ-4225R               |            |             |
| MZ-4225R    | 12V Aircraft Starter               |            |             |
| MZ-4226     | Replaced by MZ-4226R               |            |             |
| MZ-4226R    | 12V Aircraft Starter               |            |             |
| PM1201R     | 12V, 12/14 Pitch, 149 Tooth        | \$982.00   | \$100.00    |
| PM2401R     | 24V, 12/14 Pitch, 149 Tooth        | \$536.00   | \$100.00    |

page 9



Rev. Original January 2, 2013

| 4. Continen  | ital Motors Aircraft Starters » Overhaul / Exch        | nange      |             |
|--------------|--|------------|-------------|
| Part Number  | Description  | List Price | Core Charge |
| 646238-2R    | 12V Aircraft Starter                                   | \$454.00   | \$150.00    |
| 646238-3R    | 12V Aircraft Starter, w/Solenoid                       | \$500.00   | \$150.00    |
| 646275-1R    | 24V Aircraft Starter                                   | \$500.00   | \$190.00    |
| 5. Starter O | verhaul Kits   |            |             |
| Part Number  | Description  | List Price | Core Charge |
| 90-3000      | For MCL-6501   | \$240.00   |             |
| 90-3001      | For MCL-6502   | Χ          |             |
| 90-3002      | For MCL-6503   | X          |             |
| 90-3004      | For MHB-4001; MHB-4002; MHB-4003; MHB-4007             | \$458.00   |             |
| 90-3005      | For MHB-4004   | Χ          |             |
| 90-3006      | For MHB-4005   | X          |             |
| 90-3007      | For MHB-4006   | Χ          |             |
| 90-3008      | For MHB-4008   | X          |             |
| 90-3009      | For MHB-4009; MHB-4014                                 | \$486.00   |             |
| 90-3010      | For MHB-4010; MHB-4011; MHB-4012; MHB-4013             | \$458.00   |             |
| 90-3011      | For MHB-4016; MHB-4017; MHB-4018; MHB-4019,A; MHB-4020 | \$436.00   |             |
| 90-3012      | For MHJ-4002; MHJ-4003,S                               | \$264.00   |             |
| 90-3013      | For MHJ-4004; MHJ-4005                                 | X          |             |
| 90-3014      | For MHP-4004   | X          |             |
| 90-3015      | For MHP-4101   | Χ          |             |
| 90-3016      | For MMU-4001   | \$458.00   |             |
| 90-3017      | For MZ-4203  | Χ          |             |
| 90-3018      | For MZ-4204  | \$454.00   |             |
| 90-3019      | For MZ-4205; MZ-4206; MZ-4207                          | \$432.00   |             |
| 90-3020      | For MZ-4208  | X          |             |
| 90-3021      | For MZ-4214  | X          |             |
| 90-3022      | For MZ-4216; MZ-4220                                   | \$440.00   |             |
| 90-3023      | For MZ-4217; MZ-4218; MZ-4219                          | \$440.00   |             |



Rev. Original January 2, 2013

| 5. Starter Ov | verhaul Kits   |            |             |
|---------------|--|------------|-------------|
| Part Number   | Description  | List Price | Core Charge |
| 90-3024       | For MZ-4221; MZ-4222; MZ-4223; MZ-4224; MZ-4225; MZ-4226 | \$408.00   |             |
| 90-3025       | For ES646238,-2; ES646238-1,-3; ES646275, -1             | \$262.00   |             |
| 90-3026       | For MHB-6014   | \$416.00   |             |
| 90-3027       | For MHB-6016   | \$324.00   |             |
| 90-3028       | For MMU-6001   | \$420.00   |             |
| 90-3029       | For MZ-6204  | X          |             |
| 90-3030       | For MZ-6220  | X          |             |
| PM1201-OHK    | Overhaul Kit for PM1201/1202                             | \$289.00   |             |
| PM1203-OHK    | Overhaul Kit for PM1203                                  | \$289.00   |             |
| PM1204-OHK    | Overhaul Kit for PM1204                                  | \$289.00   |             |
| PM2401-OHK    | Overhaul Kit for PM2401/2402                             | \$289.00   |             |
| PM2403-OHK    | Overhaul Kit for PM2403                                  | \$289.00   |             |
| PM2404-OHK    | Overhaul Kit for PM2404                                  | \$289.00   |             |
| PM1207-OHK    | Overhaul Kit for PM1207                                  | \$237.00   |             |
| PM2407-OHK    | Overhaul Kit for PM2407                                  | \$237.00   |             |
| 90-3031       | For MZ-6222; MZ-6224; MZ-6226                            | \$406.00   |             |





Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **PARTS SECTION**

**Limited One (1) Year\* Warranty on New Components:** Read full warranty policy on page 19. For more info please visit: www.hartzellenginetech.com/aircraft-parts/aircraft-starter.html

| 6. Aircrft Sta | rter Replacement Parts   |            |             |
|----------------|--------------------------|------------|-------------|
| Part Number    | Description              | List Price | Core Charge |
| 40095          | Bendix Drive Shaft       | \$57.50    |             |
| 40102          | Comm. End Head Assembly  | \$65.50    |             |
| 40104          | Comm. End Bearing        | \$29.00    |             |
| 40106          | Drive End Head Assembly  | \$365.50   |             |
| 40106-2        | Drive End Head Assembly  | \$394.00   |             |
| 40107          | Brush Retainer Insulator | \$3.80     |             |
| 40110          | Brush Holder             | \$28.50    |             |
| 40112          | Retaining Track Plate    | \$16.50    |             |
| 50025          | Insulator                | \$6.00     |             |
| 50025          | Washer, Insulator        | \$1.60     |             |
| 50029          | Hex nut                  | \$6.50     |             |
| 50063          | Armature, 12V            | \$368.00   |             |
| 50064          | Armature Housing         | \$163.00   |             |
| 50070          | Armature, 24V            | \$368.00   |             |
| 50073          | Rubber Insert            | \$5.00     |             |
| 50074          | Thrust Ball              | \$6.50     |             |
| 50075          | Insulator - Arm Housing  | \$2.50     |             |
| 50101          | Armature Housing         | \$176.00   |             |
| 50102          | Comm. End Head Assembly  | \$65.50    |             |
| 50106          | Drive End Head Assembly  | \$365.50   |             |
| 50110          | Bendix Drive Shaft       | \$161.00   |             |
| 90-2018        | Brg & Seal Pkg           | \$53.00    |             |
| 90-2139        | Bendix Pin Pkg           | \$91.00    |             |
| 90-2140        | Bendix Pin Pkg           | \$35.00    |             |





| 6. Aircrft Sta | rter Replacement Parts           |                        |
|----------------|----------------------------------|------------------------|
| Part Number    | Description                      | List Price Core Charge |
| 90-2191        | Mounting Screw Pkg               | \$28.00                |
| 90-2232        | Thrust Washer Pkg                | \$10.50                |
| 90-2271        | Thrust Washer Pkg                | \$5.00                 |
| 90-2359        | Term Stud Pkg                    | \$12.00                |
| 90-2502        | Term Stud Pkg                    | \$54.00                |
| 90-2520        | Gear Assembly                    | \$78.50                |
| 90-2521        | Brush and Terminal Stud Package  | \$91.50                |
| 90-2522        | Hardware and Insulator Package   | \$15.00                |
| 90-2523        | Brush Spring Package             | \$8.80                 |
| 90-2524        | Through Bolt Package             | \$8.50                 |
| 90-2525        | Thrust Washer Package            | \$35.50                |
| 90-2526        | Brush Set                        | \$48.50                |
| 90-263         | Thrust Washer Pkg                | \$3.50                 |
| 90-2677        | Thrust Washer Pkg                | \$7.00                 |
| 90-2860        | Key Pkg-Bendix Drive Pkg         | \$9.00                 |
| 90-601         | Thrust Washer Pkg                | \$7.50                 |
| 90-716         | Term Stud Pkg                    | \$25.50                |
| 90-726         | Term Stud Pkg                    | \$75.50                |
| 90-876         | Term Stud Pkg                    | \$26.00                |
| 90-877         | Term Stud Pkg                    | \$28.00                |
| 2305002        | Armature, 12V, Lycoming          | \$145.00               |
| 2305003        | Armature, 24V, Lycoming          | \$164.00               |
| 2305017        | Assembly, Shaft Output           | \$80.00                |
| 5005001        | Assembly, Starter Nose           | \$193.00               |
| 5101002        | Support, Intermediate Shaft      | \$40.00                |
| 5201003        | Case, Motor, Lycoming            | \$94.50                |
| 5305001        | End Bell                         | \$50.50                |
| 5401001        | Shield, Grease                   | \$9.50                 |
| 6301003        | Label, Starter Drive Maintenance | \$2.10                 |
| 7801008        | Washer, Wave                     | \$4.20                 |





| 6. Aircrft Sta | rter Replacement Parts        |            |             |
|----------------|-------------------------------|------------|-------------|
| Part Number    | Description                   | List Price | Core Charge |
| 9005001        | Assembly, Flux Ring, Lycoming | \$147.00   |             |
| EBB-75A        | Starter Drive- Bendix         | \$171.50   |             |
| EBB-124A       | Starter Drive- Bendix         | \$179.00   |             |
| EBB-131A       | Starter Drive- Bendix         | \$147.50   |             |
| EBB-142A       | Starter Drive- Bendix         | \$179.00   |             |
| EBB-224A       | Bendix Drive                  | \$171.50   |             |
| ES1930611      | Screw Switch                  | \$3.80     |             |
| ES4243         | Thru Bolt                     | \$4.50     |             |
| ES646326       | Flange Assembly D.E.          | \$122.50   |             |
| ES646328       | Oil Seal                      | \$5.00     |             |
| ES646330       | Cover Assembly                | \$113.00   |             |
| ES646333       | Armature                      | \$277.00   |             |
| ES646351       | Coil Assembly 12V             | \$96.00    |             |
| ES646357       | Stud Terminal                 | \$11.50    |             |
| ES646359       | Washer                        | \$1.80     |             |
| ES646360       | Square Insulator              | \$6.50     |             |
| ES646361       | Washer Insulator              | \$2.00     |             |
| ES646362       | Flat Washer                   | \$2.00     |             |
| ES646363       | Lock Washer                   | \$1.80     |             |
| ES646364       | Nut Hex                       | \$4.00     |             |
| ES646365       | Hex Bolt                      | \$9.00     |             |
| ES646367       | Fiber Washer                  | \$3.00     |             |
| ES646368       | Fiber Washer DE               | \$2.00     |             |
| ES646371       | Insulator Field to Housing    | \$2.20     |             |
| ES646374       | Armature                      | \$326.00   |             |
| ES646376       | Field Coil Assembly           | \$113.00   |             |
| ES646377-2     | Housing Assembly 12V          | \$342.00   |             |
| ES646377-3     | Housing Assembly 12V          | \$342.00   |             |
| ES646378-1     | Housing Assembly 24V          | \$342.00   |             |





| 6. Aircrft Sta | rter Replacement Parts                            |            |             |
|----------------|---|------------|-------------|
| Part Number    | Description                                       | List Price | Core Charge |
| ES649107       | Solenoid 12V                                      | \$108.50   |             |
| ES649108       | Connector   | \$92.50    |             |
| ES652927       | 3/8 - 24X.670 Screw                               | \$4.20     |             |
| ES652928       | Pole Shoe Blocks                                  | \$27.00    |             |
| GJ-20DS        | Thru Bolt Pkg                                     | \$41.50    |             |
| LT-EBB-124A    | Starter Drive Kit for Lycoming 122T 03 Starter    | \$120.00   |             |
| LT-EBB-131A    | Starter Drive Kit for Lycoming 149T 01/02 Starter | \$120.00   |             |
| LT-EBB-142A    | Starter Drive Kit for Lycoming 149T 04 Starter    | \$120.00   |             |
| MBG-2012BS     | Brush Set   | \$44.00    |             |
| MBG-2012CS     | Brush Set   | \$54.00    |             |
| MBG-2012S      | Brush Set   | \$68.00    |             |
| MBP-2002D      | CE Head Assembly                                  | \$78.00    |             |
| MCL-1005PS-1   | Field Coil Pkg                                    | \$243.50   |             |
| MCL-2136       | D E Head Assembly                                 | \$141.00   |             |
| MCL-2136A      | D E Head Assembly                                 | \$141.00   |             |
| MDC-0034       | Bearing, Sleeve                                   | \$9.50     |             |
| MDL-1002B      | CE Head Assembly                                  | \$65.00    |             |
| MDL-1005FS     | Field Coil Pkg                                    | \$144.00   |             |
| MDL-1064ES     | Brush Holder Assembly                             | \$66.00    |             |
| MDL-1064G      | Brush Plate                                       | \$76.00    |             |
| MDL-2005CS-1   | Field Coil Pkg                                    | \$182.00   |             |
| MDL-2005CSS    | Field Coil  | \$354.00   |             |
| MDL-2012ES     | Brush Set   | \$32.50    |             |
| MDZ-2012CS     | Brush Set   | \$73.00    |             |
| MFX-1064AS     | Brush Plate Assembly                              | \$92.00    |             |
| MG-77A         | Bearing, DE                                       | \$6.60     |             |
| MHB-1005BS     | Field Coil  | \$105.00   |             |
| MHB-1007B      | Field Coil  | \$230.00   |             |
| MHB-2012AS     | Brush Set   | \$48.50    |             |





| 6. Aircrft Sta | rter Replacement Parts |            |             |
|----------------|------------------------|------------|-------------|
| Part Number    | Description            | List Price | Core Charge |
| MHB-2012S      | Brush Set              | \$48.50    |             |
| MHB-2384BS     | Frame & Field          | \$456.50   |             |
| MHB-2397S      | Frame & Field Assembly | \$371.00   |             |
| MHB-2399S      | Armature               | \$352.50   | \$50.00     |
| MHB-2400       | C E Head Assembly      | \$99.00    |             |
| MHB-3005AS     | Field Coil Pkg         | \$145.00   |             |
| MHB-3005BS     | Field Coil Pkg         | \$145.00   |             |
| MHB-3005S      | Field Coil Pkg         | \$145.00   |             |
| MHD-2012S      | Brush Set              | \$58.00    |             |
| MHJ-1045       | Gear Housing Assembly  | \$367.00   |             |
| MHJ-2147S      | Armature               | \$494.00   |             |
| MHJ-36         | Bearing, DE            | \$15.00    |             |
| MHJ-44         | Shaft, Bendix Drive    | \$182.00   |             |
| MHP-1002       | Spacing Ring Assembly  | \$193.00   |             |
| MHP-1005AS-1   | Field Coil             | \$100.00   |             |
| MHP-2003       | D E Head Assembly      | \$108.50   |             |
| ML-18A         | Bearing, DE            | \$5.00     |             |
| MMU-2386S      | Armature               | \$419.00   |             |
| MS16562-21     | Roll Pin               | \$1.20     |             |
| MZ-0040A       | Sleeve, Bearing        | \$5.00     |             |
| MZ-1005AS      | Field Coil Pkg         | \$154.00   |             |
| MZ-1005QSS     | Field Coil Pkg         | \$142.50   |             |
| MZ-1005RSS     | Field Coil Pkg         | \$142.50   |             |
| MZ-1024AG      | Cover Band             | \$22.50    |             |
| MZ-1236        | Int Brg Assembly       | \$41.50    |             |
| MZ-1376        | D E Head Assembly      | \$54.50    |             |
| MZ-1390        | Gear Housing Assembly  | \$117.00   |             |
| MZ-17          | Terminal, Stud         | \$24.00    |             |
| MZ-19S         | Brush Spring Set       | \$4.40     |             |
|                |                        |            |             |





| 6. Aircrft St | arter Replacement Parts                          |            |             |
|---------------|--|------------|-------------|
| Part Number   | Description                                      | List Price | Core Charge |
| MZ-2002F      | C E Head Assembly                                | \$67.00    |             |
| MZ-2002U      | C E Head Assembly                                | \$70.00    |             |
| MZ-2002V      | C E Head Assembly                                | \$77.50    |             |
| MZ-2386S      | Armature   | \$478.00   |             |
| MZ-2397S      | Field & Frame Assembly                           | \$372.00   |             |
| MZ-2399S      | Armature   | \$368.00   |             |
| MZ-2400       | C E Head Assembly                                | \$96.00    |             |
| MZ-2412S      | Armature   | \$412.00   |             |
| MZ-2413       | DE Head Assembly                                 | \$167.00   |             |
| MZ-24A        | Cover Band                                       | \$13.50    |             |
| MZ-298        | Bearing, DE                                      | \$6.00     |             |
| MZ-298-1      | Bearing, DE                                      | \$10.00    |             |
| MZ-3005GS     | Field Coil Pkg                                   | \$150.50   |             |
| MZ-326        | Shaft, BendixDrive                               | \$83.00    |             |
| MZ-326A       | Shaft, Bendix Drive                              | \$76.50    |             |
| MZ-339        | Bearing  | \$4.20     |             |
| MZ-364        | Bearing  | \$11.00    |             |
| MZ-393        | Retainer Plate                                   | \$4.50     |             |
| MZ-395        | Thrust Washer                                    | \$2.00     |             |
| MZ-396        | Gear   | \$108.00   |             |
| OHK-0001      | Kit Tools, Grease, Lycoming                      | \$32.50    |             |
| OHK-0002      | Kit, Planetary Gears, Lycoming                   | \$37.80    |             |
| OHK-0003      | Kit, Thru Bolt and Anchor Ring, Lycoming         | \$31.50    |             |
| OHK-0004      | Kit, Brush Assembly, 12V Pos - Fits 12V Lycoming | \$46.20    |             |
| OHK-0005      | Kit, Brush Assembly, 12V Neg - Fits 12V Lycoming | \$46.20    |             |
| OHK-0006      | Kit, Brush Assembly, 24V Pos - Fits 24V Lycoming | \$46.20    |             |
| OHK-0007      | Kit, Brush Assembly, 24V Neg - Fits 24V Lycoming | \$46.20    |             |
| OHK-0008      | Kit, Brush Bracket & Spring, Lycoming            | \$21.00    |             |
| OHK-0009      | Kit, Hardware, Lycoming                          | \$20.00    |             |



Rev. Original January 2, 2013

| 6. Aircrft Starter Replacement Parts |                          |            |             |
|--------------------------------------|--------------------------|------------|-------------|
| Part Number                          | Description              | List Price | Core Charge |
| OHK-0010                             | Kit, Fasteners, Lycoming | \$21.00    |             |
| PS-1432C                             | Housing, Pinion Assembly | \$287.50   |             |
| PS-1432CS                            | Housing, Pinion Pkg      | \$303.00   |             |
| PS-1432E                             | Housing, Pinion Assembly | \$364.00   |             |
| PS-1432F                             | Housing, Pinion Assembly | \$394.00   |             |
| PS-1435                              | Housing, Pinion Assembly | \$304.00   |             |
| PS-2432B                             | Housing, Pinion Assembly | \$420.00   |             |
| PS-2432BS                            | Housing & Shaft Pkg      | \$472.00   |             |
| X-3991                               | Bearing, Ball            | \$19.50    |             |
| X-5384                               | Bendix Pin               | \$5.60     |             |
| XA-0997                              | Needle Bearing           | \$15.50    |             |
| XA-0998                              | Needle Bearing           | \$19.50    |             |
| XA-1024                              | Oil Seal                 | \$17.00    |             |
| XA-1026                              | Seal, Shaft              | \$8.00     |             |
| XA-560                               | Oil Seal                 | \$25.00    |             |



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **GENERAL WARRANTY POLICY**

# 7. Limited Warranty Policy

Hartzell Engine Technologies LLC (HET) warrants that all new, rebuilt or overhauled products (or minor revision derivatives thereof), sold by Hartzell Engine Technologies LLC, Montgomery, Alabama, shall be free from defects in material and workmanship under normal use and service for a period of:

| New E-Drive, M-Drive & Energizer<br>Aircraft Starters | New X-Drive Aircraft Starters                       |
|---|---|
| 2 Years* Unlimited Hours                              | 2 Years* Unlimited Hours<br>(Kickbacks not covered) |

| New Replacement Components & MHB, MHJ, MZ Aircraft Starters | Overhauled Starters |
|---|---------------------|
| 1 Year* Unlimited Hours<br>(Kickbacks not covered)          | 6 Months*           |

The warranty period begins (unless otherwise noted) from the date of installation into the aircraft if, and only if, the following conditions are met:

- A. The unit and warranty claim, with all requested information properly supplied has been returned to any authorized Hartzell Engine Technologies LLC, distributor. International Customers may utilize a HET Authorized Service Center or a HET Distributor. Units must be returned within 30 days of the product failure date.
- B. No substitute parts shall have been installed in the product without prior authorization of Hartzell Engine Technologies LLC, Montgomery, Alabama USA.
- C. The product shall not have been disassembled, repaired, or altered outside of HET approved facilities unless express prior authorization was granted in writing.
- D. The product shall not have been subject to misuse, accident, or improper installation unless proof is submitted to the satisfaction of Hartzell Engine Technologies LLC, that such abuse was not a cause for the claimed defect.
- E. The duration of this Limited Warranty shall be for the unused portion of the original warranty period. Any replacement unit or repair shall not establish a new warranty period.



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

NOTE \* Units will be activated automatically for a shelf stock warranty period and in all cases shall expire thirty-six (36) months from date of manufacture (see I.D. plate). Units held in distribution stock over thirty-six (36) months can be returned to the factory for complete testing, recertification, new warranty, and new packaging for a charge of 20 percent of list price.

### 8. Limitations and Exclusions

- A. The sole responsibility and liability of Hartzell Engine Technologies LLC and your exclusive remedy under this claim arising out of, connected with, or resulting from, this sale or the performance or breach of any condition or warranty thereunder, or from the manufacture, delivery, or use of the product shall be the repair of, or replacement, or credit for this defective product at Hartzell Engine Technologies LLC's option.
- B. IN NO EVENT. WHETHER AS A RESULT OF A BREACH OF CONTRACT. WARRANTY. TORT (INCLUDING NEGLIGENCE), OR OTHERWISE, SHALL HARTZELL ENGINE TECHNOLOGIES BE LIABLE FOR ANY SPECIAL, CONSEQUENTIAL, INCIDENTAL, OR PENAL DAMAGES OR EXPENSES, INCLUDING BUT NOT LIMITED TO, COSTS OF REMOVAL AND REPLACEMENT OF THE PRODUCT(S), LOSS OF PROFIT, GOODWILL, OR REVENUES, LOSS OF USE OF THE PRODUCT OR ANY ASSOCIATED EQUIPMENT, DAMAGE TO ASSOCIATED EQUIPMENT, COST OF CAPITAL, COST OF SUBSTITUTE PRODUCTS, FACILITIES, OR SERVICES, DOWN TIME, OR COSTS OR CLAIMS OF THIRD PARTIES FOR SUCH DAMAGES OR EXPENSES.

# 9. Warranty Registration

- A. Warranty Registration is required on every new unit sold by Hartzell Engine Technologies LLC and sold through an authorized Hartzell Engine Technologies distributor.
- B. Warranty Registration must be completed by logging on to the internet via www.HartzellEngineTech.com and following the path to warranty registration. The installing agency must file the registration showing all information required therein. The warranty registration must be accomplished within 10 days of the date of installation or this warranty is void.
- C. An owner copy of the warranty registration may be printed out once registration is completed and should be kept with the aircraft's log book and/or paperwork file carried in the aircraft. When requesting warranty consideration, the Warranty Registration copy should be returned with the unit to an authorized Hartzell Engine Technologies distributor along with information pertaining to the removal and installation dates and suspected difficulty.



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# 10. Specific Terms

- A. The foregoing warranty is exclusive and in lieu of all other warranties or remedies whether written, oral, implied, or statutory. Any and all implied warranties of merchantability, fitness for a particular purpose, course of dealing or usage of trade are hereby expressly disclaimed and excluded. The Warranty Registration must be completed within 10 days from the date of installation of the equipment or this warranty is void.
- B. Acceptance of the product by you shall constitute your acknowledgment and acceptance of the terms, provisions, limitations, and exclusions set forth herein. Such terms, provisions, limitations, and exclusions shall not be modified, deleted, or supplemented except by an express written acknowledgment of Hartzell Engine Technologies.

### 11. General

- A. Any claims under this warranty should be made through a Hartzell Engine Technologies LLC authorized distributor or service center. Any claim made, which cannot be reasonably duplicated, will not be considered applicable to warranty and shall be returned "as is". All claims shall be handled according to standard warranty procedures; see your authorized distributor for details. A list of HET distributors may be obtained from Hartzell Engine Technologies LLC via Internet at www.HartzellEngineTech.com or by Tel: (334) 386-5400.
- B. All products returned by a distributor for warranty consideration are to be shipped to Hartzell Engine Technologies LLC, 2900 Selma Highway, Montgomery, Alabama 36108 (USA) freight prepaid. If the warranty claim is accepted, the replacement parts, if shipped individually, will be shipped surface freight, prepaid.



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

# **CORE RETURN & RETURN GOODS POLICY**

# 12. Core Return Policy

Any unit being returned for core or warranty core credit shall be, as removed from the engine, complete and not disassembled. No core or warranty core credit will be allowed for automotive units. Units that are rusty or cannot be overhauled for any reason will be classified as scrap, having no value. Units which have been weld repaired, as well as units which have been disassembled and then reassembled with old parts, will also be classified as scrap, having no value. A percentage of the core value will be charged for all missing or damaged parts. At no time will the damaged or missing parts charge on any unit exceed the core value of that unit.

- Cores will only be accepted for credit 12 months from date of invoice.
- Cores returned in excess of cores invoiced will become the property of Hartzell Engine Technologies LLC and will only be credited for up to 10% of core value.
- Cores must be of like purchase or a direct superseded unit.

| Description  | Percentage of Core Charge                                  |
|--|--|
| STARTERS » Hardware Missing Gear Missing or Sub-Shaft Damaged Armature Frozen/Binding or Switch Missing Lever Missing Armature Missing Drive End Housing Damaged/Missing End Frames-Elongated Bolt Holes/Missing Housing or Locating Pins Damaged Intermediate Gear HsgMissing/Damaged | 5%<br>10%<br>20%<br>22%<br>25%<br>35%<br>35%<br>35%<br>35% |



2900 Selma Highway Montgomery, AL 36108 USA

Phone (334) 386-5400 Fax (334) 386-5410 www.HartzellEngineTech.com

### **CORE RETURN ADDRESS:**

Hartzell Engine Technologies LLC 4570 Newcomb Avenue Montgomery, AL 36108 USA

Please feel free to contact us if you have any questions or concerns regarding your returned goods; (877) 359-5355 Toll free » (334) 386-5400 Phone » (334) 386-5410 Fax

### 13. Return Goods Policy

Hartzell Engine Technologies will accept returned goods with the following conditions:

- A. The part must have been originally purchased from Hartzell Engine Technologies LLC and must be a current production part.
- B. Parts may be returned within 90 days after invoice without restocking charge as long as the product is in its original packaging.
- C. Parts returned after 90 days are subject to a minimum of 20% restocking charge. No merchandise may be returned after one year.
- D. All returns must include: Date of purchase, Hartzell Engine Technologies LLC invoice number, and the reason for return.